


ACCESS 8 AH V2.0 Installation note

1. Add 1nF capacitors between WIE0 & GND and WIE1 & GND as in picture 1 to improve Wiegand signal quality.



Picture 1. Adding capacitors to WIE-lines